

RECORDS NOTE

CORRECT RECORD MEASUREMENT
AS FOLLOWS: 2. CRW-1 EXIST
BETWEEN P2 AND P12 AND
THE CORRECT R.P.M. IS 3725.

NOTES

- (1) RECORDS: CHANGE
RC TO 15
- (2) APCO TO PL 4- 40-5
APOLES AT LOC. **A**
- THRU **B**
- (3) APCO TO PL 2 - 40-
JLV. ARE AT LOC. **A**
- AND **B**
- (4) APCO TO BULL SCS
18200 MR. LINE 580

CAUTION!
CHECK FOR DEFECTIVE
WIRING BEFORE CLEANING

SAFETY IS NO ACCIDENT

ATTENTION: 1st PAGE ONLY

CAUTION!
LOCATE ALL BURIED
UTILITIES BEFORE
DIGGING.

T D G A.

CAUTION: 5.1 MHz
VOLT: 7.2 V.

FOR NOT STAKED
CONTACT ENGINEER
3 DAYS PRIOR TO
CONST. 972-2646

STATE OF ALABAMA
I CERTIFY THIS
INSTRUMENT WAS FILED

1984 MAR -9 AM 8:06

JUDGE OF PEACE

Due TAX. 50
 Rec 3.00
 Ind 1.00
4.50